



# Product Change Notice

## (產品變更通知)


<b>Changed Product (變更的產品):</b> HERCULES-PB Series SLC/MLC in G5/G5L/G4SB USB 2.0 Flash Disk	<b>Doc. No.(文件編號):</b> PCN_099-XXUFD_PB2PD_1V0
	<b>Date(日期):</b> 2019/08/16
<b>Change Description and the reasons (變更說明與變更緣由):</b> 因為 Controller design house 生產 SM3257 BA 光罩毀損,無法在生產. 因此改以 SM3257 BB 取代. PCB & Firmware 不變, 但 MP Tool 改版。 The production is discontinued because of the controller's (SM3257 BA) Mask was damaged. Therefore, we applied the enhanced version controller SM3257 BB.	
<b>Key Dates (關鍵日期):</b> EOL 時間 2019/09/01 Last Buy 時間: 2019/12/01 新樣品可下單時間:2019/08/26 EOL by 2019/09/01 Last Buy Time by 2019/12/01 New product is available by 2019/08/06	

### Comparison A: Product Specification

Before Change (產品變更前)				
Flash	Category	Series	Spec-sheet	Capacity
SLC	UFD_G4SB	HERCULES-PB	<a href="#">Download</a>	128MB up to 16GB
	UFD_G5		<a href="#">Download</a>	128MB up to 16GB
	UFD_G5L		<a href="#">Download</a>	16GB up to 32GB
MLC	UFD_G4SB		<a href="#">Download</a>	4GB up to 64GB
	UFD_G5		<a href="#">Download</a>	4GB up to 64GB
	UFD_G5L		<a href="#">Download</a>	64GB up to 128GB
After Change (產品變更後)				
Flash	Category	Series	Spec-sheet	Capacity
SLC	UFD_G4SB	HERCULES-PD	<a href="#">Download</a>	128MB up to 8GB
	UFD_G5		<a href="#">Download</a>	128MB up to 8GB
	UFD_G5L		<a href="#">Download</a>	16GB
MLC	UFD_G4SB		<a href="#">Download</a>	4GB up to 32GB
	UFD_G5		<a href="#">Download</a>	4GB up to 32GB
	UFD_G5L		<a href="#">Download</a>	64GB



Comparison B: Controller & PCB

Differentiation (說明)	Before Change (產品變更前)	After Change (產品變更後)
Front View		

APRO Co., Ltd.

Andy Lin /Product Manager  
2019/8/16